



04/14/04
SN 10/663,130

CofC
H

FOR COURIER DELIVERY ONLY

5445 CORPORATE DRIVE
TROY, MICHIGAN 48098
(248) 641-1600

HARNESS, DICKEY & PIERCE, P.L.C.
ATTORNEYS AND COUNSELORS
P.O. BOX 828
BLOOMFIELD HILLS, MICHIGAN 48303
U.S.A.

CABLE
PATENTS TROY, MICHIGAN
TELEX NO. & REPLY
287637 HARNES UR
TELEFACSIMILE
(248) 641-0270

September 13, 2004

**Express Mail Label
No. EV 531 989 892 US**

Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450

Re: U.S. Patent No. 6,773,242 B1
Issued August 10, 2004
For: Scroll Compressor with Vapor Injection
Michael M. Perevozchikov, Inventor

**Certificate
SEP 20 2004
of Correction**

Dear Sir:

We have noted, in proofreading the subject patent, the errors listed on the enclosed Certificate of Correction form. Our records indicate that these errors were made by our office. Our check for \$100.00 is enclosed.

The corresponding location in the application of the errors in question is as follows:

The first error appears on page 7, line 22 of the application.

The second error appears on page 8, line 4 of the application.

The third error appears on page 8, line 10 of the application.

The fourth error appears on page 8, line 10 of the application.

The fifth error appears on page 9, line 4 of the application.

The sixth error appears on page 9, line 10 of the application.

The seventh error appears on page 2, line 11 of the amendment dated September 16, 2003.

The eighth error appears on page 11, line 5 of the application.

09/15/2004 CNGUYEN 00000048 6773242

01 FC:1811

100.00 US

EV 531 989 892 US

21 SEP 2004

Please certify the enclosed Certificate of Correction and return same to us.

Very truly yours,

By


Charles H. Blair
Registration No. 19734
(Attorney for Applicant)

CHB/d
0315-000523/DVA

21 SEP 2004

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO : 6,773,242 *B1*

Page 1 of 1

DATED : August 10, 2004

INVENTOR(S) : Michael M. Perevozchikov

It is certified that error appears in the above-identified patent and that said Letters Patent are hereby corrected as shown below:

Column 4, line 12, "sealing" should be -- sealingly --.

Column 4, line 19, "Member" should be -- member --.

Column 4, line 27, "Coupling" should be -- coupling --.

Column 4, line 28, "key" should be -- keys --.

Column 4, line 51, "88" should be -- 58 --.

Column 4, line 57, "horizontal" should be -- horizontally --.

Column 5, line 10, "1 7Q0" should be -- 170° --.

Column 5, lines 43-44, "enclosed's pace" should be -- enclosed space --.

MAILING ADDRESS OF SENDER: Harness, Dickey & Pierce, P.L.C.
P.O. Box 828
Bloomfield Hills, MI 48303

PATENT NO. 6,773,242 *B1*

No. of additional copies



This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.

If you need assistance in completing the form, call 1-800-PTO-9199 and select option 2.

21 SEP 2004